CITY OF GRIFFIN, GA

	Coke Tank				
Project	Tank Name	Tank Information	Task Name	Status	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Exterior Renovation	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Washout/Disinfect	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Interior Renovation	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Chemical Clean Washout	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Chemical Clean Washout	Scheduling	
112572	COCA COLA PLANT TANK	1,000,000 ELEVATED	Exterior Renovation	Future	
		Industrial Tan	k		
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Exterior Renovation	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Washout/Disinfect	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Interior Renovation	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Visual Inspection	Completed	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Chemical Clean Washout	Completed	
440=00	INIDIICTDIAL DADICTANIC	4 000 000 ELEVATED	Chemical Clean Washout	Cchaduling	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED		Scheduling	
112598 112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED	Exterior Renovation	Future	
112598	INDUSTRIAL PARK TANK	1,000,000 ELEVATED By Pass Tank	Exterior Renovation	Future	
112598 112637	INDUSTRIAL PARK TANK BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Exterior Renovation Visual Inspection	Future Completed	
112598 112637 112637	INDUSTRIAL PARK TANK BY-PASS TANK BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation	Future Completed Completed	
112598 112637 112637 112637	BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation	Completed Completed Completed	
112598 112637 112637 112637 112637	BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection	Completed Completed Completed Completed	
112598 112637 112637 112637 112637	BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection	Completed Completed Completed Completed Completed Completed	
112598 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect	Completed Completed Completed Completed Completed Completed Completed	
112598 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection	Completed Completed Completed Completed Completed Completed Completed Completed	
112598 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout	Completed Completed Completed Completed Completed Completed Completed Completed Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Exterior Renovation Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection	Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout	Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation	Future Completed Future	
112598 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation	Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED Harry Simmor	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation	Future Completed Completed Completed Completed Completed Completed Completed Completed Completed Future Future	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637	BY-PASS TANK	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation Interior Renovation	Future Completed Completed Completed Completed Completed Completed Completed Completed Completed Future Future Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637	INDUSTRIAL PARK TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK WATER PLANT STANDPIPE WATER PLANT STANDPIPE	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 STANDPIPE 530,000 STANDPIPE	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation Interior Renovation Exterior Renovation Exterior Renovation	Future Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637	INDUSTRIAL PARK TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK WATER PLANT STANDPIPE WATER PLANT STANDPIPE	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 530,000 STANDPIPE 530,000 STANDPIPE	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Inspection Exterior Renovation Interior Renovation Exterior Renovation Exterior Renovation Visual Inspection	Future Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 114862 114862 114862 114862	INDUSTRIAL PARK TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK WATER PLANT STANDPIPE WATER PLANT STANDPIPE WATER PLANT STANDPIPE WATER PLANT STANDPIPE	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 530,000 STANDPIPE 530,000 STANDPIPE 530,000 STANDPIPE	Visual Inspection Interior Renovation Exterior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation Exterior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect	Future Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 114862 114862 114862 114862 114862	BY-PASS TANK WATER PLANT STANDPIPE	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 1,000,000 STANDPIPE 530,000 STANDPIPE 530,000 STANDPIPE 530,000 STANDPIPE	Visual Inspection Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation Interior Renovation Exterior Renovation Visual Inspection Visual Inspection Visual Inspection Visual Inspection Visual Inspection Visual Inspection	Future Completed	
112598 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 112637 114862 114862 114862 114862	INDUSTRIAL PARK TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK BY-PASS TANK WATER PLANT STANDPIPE WATER PLANT STANDPIPE WATER PLANT STANDPIPE WATER PLANT STANDPIPE	1,000,000 ELEVATED By Pass Tank 1,000,000 ELEVATED 530,000 STANDPIPE 530,000 STANDPIPE 530,000 STANDPIPE	Visual Inspection Interior Renovation Exterior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect Visual Inspection Chemical Clean Washout Visual Inspection Chemical Clean Washout Exterior Renovation Interior Renovation Exterior Renovation Exterior Renovation Visual Inspection Visual Inspection Washout/Disinfect	Future Completed	

114862	WATER PLANT STANDPIPE	530,000 STANDPIPE	Chemical Clean Washout	Scheduling		
114862	WATER PLANT STANDPIPE	530,000 STANDPIPE	Exterior Renovation	Future		
114862	WATER PLANT STANDPIPE	530,000 STANDPIPE	Interior Renovation	Future		
	Harry Simmons					
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Exterior Renovation	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Interior Renovation	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Visual Inspection	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Visual Inspection	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Chemical Clean Washout	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Washout/Disinfect	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Visual Inspection	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Chemical Clean Washout	Completed		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Visual Inspection	Scheduling		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Repair	Scheduling		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Exterior Renovation	Future		
114871	WATER PLANT ELEVATED TANK	75,000 ELEVATED	Interior Renovation	Future		

Date

- 21-Dec-05
- 4-May-06
- 13-Oct-06
- 8-Mar-07
- 24-Sep-08
- 30-Sep-08
- 6-May-09
- 14-Apr-10
- 25-Jul-11

2013

2014-2015

- 31-Oct-05
- 25-Aug-06
- 13-Oct-06
- 15-Mar-07
- 1-Feb-08
- 1-Dec-08
- 3-Dec-09
- 14-Apr-10

24-Mar-11

2013

2014-2015

- 23-Nov-05
- 18-Jan-06
- 25-Aug-06
- 23-Oct-06
- 7-Mar-07
- 18-Mar-08
- 7-May-09
- 12-Jan-10
- 25-Jul-11

2013

2016-2017

2018-2020

- 13-Sep-06
- 14-Sep-06
- 9-Feb-07
- 19-Mar-08
- 17-Apr-09
- 17-Feb-10
- 18-May-11

2013

2016-2017

2018-2020

28-Feb-07

28-Feb-07

23-Mar-07

1-Feb-08

17-Apr-09

12-Jan-10

18-May-11

21-Feb-12

2013

2013

2017-2018

2019-2021